RV8 heater rail modification to avoid a heavy indentation on a rubber heater hose





Heater rail pipe showing the alternator bolt that can get pushed into the rubber hose below – it's just in view bottom left of photo above



Steve Newton has come across a number of RV8s with an indentation on an elbow shaped rubber heater hose on the end of the heater rail near the alternator. The heavy indentation is made by a bolt head on the alternator cradle pressing against the rubber tubing. Steve says it's not seen on every car so why does it appear on some RV8s?

the manufacture of the heater rails there was some variability in the positioning of the welded brackets on the rail so when the heater rail is bolted down with the fixing bolts, the end of the rail near the alternator is too close to the alternator. So the elbow is pressed up hard against the bolt head on the alternator. The cure is not to bolt up rail to the fixing

Above: showing the front cover to heater rail hose in place. The heater rail runs along the top of the engine back to the heater and is fixed by a bracket across the engine

It seems that in



point

Above: showing one of the two fixing bolts that hold the heater rail pipe in place, these can be removed to allow the heater rail to be moved forward but must be put back to hold the fuel rail in place.