

What does a corroded Dunlop composite wheel look like?



Above is an example of a Dunlop composite wheel on an MGBGTV8 “barn find” which was in a seriously corroded condition. The chromed steel rim is looking rough and the section of the rim near the alloy centre is particularly corroded.

The wheels refurbishment specialist **Motor Wheel Service** (“MWS”) based in Slough in Berkshire sadly ceased providing its high quality comprehensive refurbishment service for Dunlop composite wheels in 2016. See the NEWS item released then:

<https://www.v8register.net/sub/news160722MW Sends.htm>

What are your options if your Dunlop composites are corroded and need of refurbishment?

<https://www.v8register.net/subpages/V8NOTE575.htm>

Refurbishing a set of Dunlop composite wheels

Here Mike Breedon describes his experience with a set of wheels for one of his MGBGTV8s.

<https://www.v8register.net/subpages/V8NOTE583.htm>