

MGBGTV8 rebuild report from Lorraine Noble-Thompson



Geoff Allen (who was in Rectifications for 27 years) said fitting the headlining was a difficult task but it now in place. Windscreen & tailgate soon to go in.





Air intake in front of the windscreen with an aftermarket mesh which keeps leaves out so they don't collect at the bottom of the air chamber with road dust.



Upgraded front light & side light units fitted – the old sealed beams provide as much head lighting as candles! An upgrade well worth making.



Following the respray the rebuild is progressing well with refitting the re-chromed rear bumper, the rear light units, reversing lights and the headlights too. Inside the carpet trim on and around the luggage platform is progressing and the rear bench seat back is now reinstalled together with the recoil seat belts.