## List of Best RV8 Mods

- 1. Rechipping an RV8 engine (options)
- 2. Fitting a PAS or an EPAS system (options)
- 3. Fitting a windstopper/wind deflector (options)
- 4. Replacing the plastic coolant filler plug with a brass or stainless steel unit
- 5. Adjusting tyre pressures on an RV8
- 6. Fitting new tyres
- 7. Changing to silicone brake fluid
- 8. Fitting a Hoyle IRS upgrade
- 9. Converting an RV8 to LPG whilst retaining the option to run on petrol
- 10. Fitting a cooling fan override switch
- 11. Fitting a cooling fan run-on unit
- 12. Fitting gas struts to an RV8 bonnet
- 13. Fitting electric wing mirrors
- 14. Fitting replacement clear indicator lenses
- 15. Fitting a remote controlled central locking system
- 16. Fitting electric windows
- 17. Fitting a replacement performance exhaust system
- 18. Fitting replacement polyurethane front suspension bushes
- 19. Fitting replacement polyurethane engine mounts
- 20. Replacing the front grilles with stainless steel replacements
- 21. Restoring the roadwheels originally supplied with the RV8
- 22. Replacing the original wheels with 17 inch Compomotive
- 23. Shot blasting and zinc plating the front suspension crossmember
- 24. Fitting a set of bespoke Spax shock absorbers on the RV8

- 25. Modifying the handbrake so it is not so close to the steering wheel
- 26. Installing a Thatcham 1 security system
- 27. Replacing the original leather gearknob with an Elm burr "Starkey"
- 28. Creating a soft bag to slip over unzipped rear window to prevent scratching
- 29. Refurbishing the interior Elm burr trim when it is cracked
- 30. Replacing a corroded windscreen surround
- 31. Fitting a boot luggage rack
- 32. Replacing the electronic ignition amplifier
- 33. Removing the longer section of rubber bonnet seal next to the windscreen to allow engine heat to escape
- 34. Lowering the driver's seat so a tall bodied driver sits lower in the car
- 35. Replacing the clock with an oil pressure gauge
- 36. Changing the coolant temperature gauge to show the real temperature
- 37. Removing the air conditioning equipment
- 38. Replacing aircon air intakes with spot or fog lights
- 39. Removing the Rover badges on the wings
- 40. Removing or replacing the CD player

V8 Register – MG Car Club 121106-Best-RV8-Mods-list-R3 1