Brackets for the brake servo – MGBGTV8



Bob Grieves, with a relatively late rubber bumpered MGBGTV8 (Black 2788), raised a query on the V8BB saying "does anyone know what is supporting the end of the brake servo? Mine is just held in place by the P bracket on the casting where the pipes are connected. I've taken off the washer bottle holder and there is not, and never has been, anything fitted to the 3 studs on the end of the servo! Problem is, I removed a cloth from behind the servo, and now it vibrates against the bulkhead. Yes I know - put the cloth back - but this is not an "engineering" solution."


Dave Wellings responded saying "it's been a long time since I removed one, but I know there is a bracket with a stud which passes through the bulkhead into the passenger footwell, where there is a nut and washer. There is also, as far as I recall, a nut into the bulkhead somewhere around the washer bottle carrier. It sounds like yours may be missing.

Matteo Masi,a V8 enthusiast in Italy, then provided a definitive reply "the servo has two brackets - BHH1149 (at the front) and BHH1148 (at the rear, to be fitted to the three studs on the end of the servo). It seems your car is missing the second one. The servo could be fitted with the only rear bracket, which is the bigger one, but it won't be firmly secured with the only front bracket. Both items are NLA but Moss and other spares suppliers sell a bracket kit including both brackets. As I am missing the front bracket please let me know if you want to buy a kit - we could buy it together."

Bob Grieves later returned saying "now that I have removed the washer bottle holder, I can see that the rear bolt goes through to the footwell and has a rubber

plug in it, the front bolt also holds the washer bottle holder in place. I had this discussion with someone at the MG Car Club on Monday and he suggested that as it was a 1976 (Feb) car, it should have the servo on the back of the peddle box. But it seems that this was not the case with the MGBGTV8s.

Thanks for all your help and a front bracket will be flying down to Italy soon. It did cross my mind that Matteo's car was either in front or behind mine when they came down the production line, as he is missing the front bracket!"



Source: Parts Catalogue MGB Tourer, GT and V8 up to September 1976 AKM0039 (February 1977 1st Edition) page 108-G 49 Servo system RHD and V8

III. No.	Part No.	111111	DESCRIPTION	Qty.	Change Point	1	REMARKS
		SERVO S	YSTEM RHD AND V8				
1	BHA 5076	SERVO ASSEMBLY \$1					
2	37H 3812						
3	37H 4896		on-return				
4	27H 2929	Key		NLA			
5	27H 9314	Push-ro	d	1			
6	27H 9316	Bearing.		1			
7	27H 9317	Plate-ab	outment	1			
8	27H 9318	Screw-s	hell to body	3	NO. 1		
9	27H 9319		eturn				
10 37H 3813		Piston-v	acuum	NLA	Sam peror to		
11	27H 9309		-lower		SERVICE STATE		
= 12	27H 9311	Diaphra	gm-air control valve	1			
13	27H 9321		giri dii oonii oi rairoiiiiiii				
14	37H 3251						
15	BHH 1149		T ASSEMBLY				
	SH 604061		T AGGEWIDE T				
	PWZ 104		-plain				
	LWZ 204	Washer.	spring	1	(C)G-HN5-328101 TO		
	NH 604041		opring		410000		
	PMZ 310		acket		(C)G-HN5-328801 TO		
	PWZ 103		olain		410350		
	LWZ 203	Washer-s	spring	1	(C)G-D2D1-101 TO	4	
	ANZ 103		pring		2903	\blacksquare	-
16	A STATE OF THE PARTY OF THE PAR		ear		2000		
	WL 600051		spring		man train, an		
	PWZ 105	Washer	olain	1	111111111111111111111111111111111111111		
	HZS 506		//all1		图 (D) 图 (N) (D) (D) (D) (D) (D)		
	21A 2255				THE WILLIAM ST	7	
	BHA 5044		manifold		ACTUAL COLUMN S	N	ot V8
17	BHA 5039	Hose vac	uum	4	1000	V	
	AHC 234		3				
14	PMZ 316		se to bulkhead			7	
	PWZ 203	Wacher-	olain	1			
	WL 700101	Washer	spring	1		N	ot V8
	AHC 735	Dioco die	stance	NI A		1 "	01 10
	7H 7851		starice			_	
	233220						
The second secon	3H 550						
	FNZ 105	Nut-con	o to rear bracket	3	PROBLEM AND ADDRESS		
	WL 600051		spring		a strong to be tree.		
	HZS 406	Scrowers	ear servo bracket to		In the same of the same and		
	1120 400		di servo bracket to	1	White with parties to		
	PWZ 204		plain		of advances		
	LNZ 104		piain			-	
	LIVE 104	14UL			LICIO-MNO, S-MUD		

Source: Parts Catalogue MGB Tourer, GT and V8 up to September 1976 AKM0039 (February 1977 1st Edition) page 108-G 50 Servo system RHD and V8