

RV8 wheel refurbishment photos



Left: wheel before refurbishment with lacquer lifting. **Top:** high quality of the refurbishment of the wheel centre and cap. **Above left and right:** overall effect of the refurbishment is excellent. Following the work carried out by the wheel specialists Lepsons in Kent. (Photos: Al Barnett)